

## MISSOURI DEPARTMENT OF HEALTH AND SENIOR SERVICES STATE PUBLIC HEALTH LABORATORY

#### ALCO-SENSOR IV WITH PRINTER MAINTENANCE REPORT

**RECEIVED** 

By Carol Day at 1:27 pm, Jul 09, 2015

Complete this report in duplicate at the time of the regular monthly preventative maintenance check, and whenever instrument is repaired. Send copy to Department of Health and Senior Services; retain original in department file.							
ALCO SENSOR IV SN 105449	PRINTER SN 097.3585.012			DATE OF INSPECTION			
LOCATION OF INSTRUMENT (STREET AND CITY) 200 HIGHLANDS BLVD DR MANCHEST		TIME OF INSPECTION 2246					
CHECKLIST: Place a mark in the box by each item if found to be satisfactory or if operating within established limits. (Write in observed val-							
ues where determined.) Unmarked items must be corrected before using instrument.							
DIGITAL READOUT (ALL ELEMENTS OPERATIONAL)							
TEMPERATURE OF ALCO SENSOR (10°C - 40°C) 23°C							
PRINTER WORKING PROPERLY	PRINTER WORKING PROPERLY						
TIME AND DATE DISPLAYING PROPERL	_Y		HADICESONIONING INSISTIN'S PRIMERY PORTICON CONTROL OF THE STATE OF TH				
BREATH ALCOHOL ACCURACY STANDARD	OS						
SIMULATOR SOLUTION		COMPRESSE	D ETHANOL-GA	AS MIXTURE			
STANDARD SUPPLIER GUTH	L	OT# /4220	EXP. DATE	09-24-	2016		
SIMULATOR TEMPERATURE (34°C ± 0.2	2°C) <u>34.0° C</u> SIMI	JLATOR SN 502	<u> </u>	ATOR EXP DAT	E/2/2-201		
Run three tests using a standard solution. All three tests must be within ±5% of the standard value and must have a spread of .005 or less. Check the box corresponding to the standard solution being used. (PRINTOUT ATTACHED)  0.100% STANDARD - MUST READ BETWEEN 0.095% and 0.105% INCLUSIVE  0.080% STANDARD - MUST READ BETWEEN 0.076% and 0.084% INCLUSIVE  0.040% STANDARD - MUST READ BETWEEN 0.038% and 0.042% INCLUSIVE							
TEST 1 - , 098 TI	EST2 . 09	7	TEST 3 • . 096				
RFI DETECTOR OPERATING							
INDICATE THE NUMBER OF BREATH TESTS IN THE FOLLOWING RANGES SINCE THE LAST MAINTENANCE REPORT: (DO NOT INCLUDE SELF-ADMINISTERED TESTS)							
REFUSALS (004)	(.0509)	(.1014)	(.1519)	O (OVER	10)		
List any new parts and describe any alteration or modification that was made to restore the instrument to operate satisfactorily and within established limits (use other side if necessary).							
INSPECTING OFFICER	necessary of the second of the						
SIGNATURE SIGNATURE	SGT MUSS						
TYPE II PERMIT NUMBER/EXPIRATION DATE		TELEPHONE NUMBER (636) 227-1410					
236298 //-26-15 (636) 227-1410  Return completed report to the: Breath Alcohol Program, MO Department of Health and Senior Services, Southeast District Office							
2875 Jame	es Boulevard ff, MO 63901	amontorroundant a	A COMO CONTO	oo, oodineast D	ISTRICT OTHER		

	AS IV Serial no: 185449	Version no: 532B	TEST RECORD 00227	Temp Date Time 218L	Air Blank:	87/87/15 ZZ:49 .eee Calibration Check:	73 0//0//12 75-75	Subject Name		Subject I.D.		Operator Name, J.D.	35	Location		
AS IV Serial no: 185449	Version no: 532B	TEST RECORD 00228	Temp Date Time 2101	Air Blank:		25 07/07/15 22:51 ,097	Webert Mase		Subsect L.D.		ureratur Name, I.D.	18W8	location			
AS IV Serial no: 185449 Version no: 532B	TEST RECORD 00229 s/	Temp Date Time 210L	Air Blank: 87/87/15 02:53 888	Calibration Check: 25 87/87/15 22:53 .096		Subsect Mame	The second secon		Operator Name, I.D.	1503	Location		Annual transfer and the court of a conference of the court of the cour		The state of the s	

AS IV Serial no: 105449
Version no: 532B

TEST RECORD 00230
s/
Temp Date Time 210L

VOID: RFI
12 07/07/15 22:54

Subject Name

Subject I.D.

Operator Name, I.D.

Location



#### CERTIFICATE OF ANALYSIS

Certified Alcohol Reference Solution for Simulator

Random Samples of Lot Number 14220 of Alcohol Reference Solution for Simulator were analyzed by gas chromatography on September 25, 2014, using a Perkin Elmer Gas Chromatograph Autosystem XL S/N: 610N9030209, and found to contain 0.1209% (w/vol) ethyl alcohol. The expiration date for this lot number is September 24, 2016 at 11:59 PM.

When used in a calibrated Simulator, operating at 34°C +/- .2°C, this solution will give a breath alcohol analysis instrument reading of 0.100 g/210L +/- 3%.

The alcohol and water used in this solution were free of test interfering substances.

Ted L. Pauley, President GUTH LABORATORIES, INC.

NIST Traceability:

Testing was conducted using Cerilliant Reference Standard lot number FN08051301 whose values are traceable to NIST.

All balances are calibrated annually by an outside agency using NIST traceable weights. Calibration verification is done prior to each use utilizing NIST traceable weights.



### STATE OF MISSOURI

DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM



# PERMIT TYPE II DAN E WEST

is hereby authorized to instruct and supervise operators, train instructors, inspect, calibrate, perform field service and repairs, and operate the following breath analyzer(s):

### INTOXILYZER 5000, INTOX EC/IR II, ALCO-SENSOR IV W/PRINTER

for the determination of the alcoholic content of blood from a sample of expired air. Permit issued under the provisions of sections 577.020 through 577.041, RSMo and 306.111 through 306.119 RSMo.

DATE	11/26/2013	hu no
DATE		DIRECTOR OF STATE PUBLIC HEALTH LABORATORY
NUMBER	230298	Dal Vasterly
EXPIRES	11/26/2015	,acting director
		DIRECTOR OF DEPARTMENT OF HEALTH AND SENIOR SERVICES
HO 580 0 1415	+ 17i)	# AB-4 (R6-10)

STATE OF MISSOURI
DEPARTMENT OF HEALTH AND SENIOR SERVICES
BREATH ALCOHOL PROGRAM

INSTRUMENT OPERATOR CARD

The named cardholder is authorized to operate an evidential breath alcohol
instrument for the determination of the alcoholic content in breath form of expired air
in Missouri.

Operator WEST, DAN
Permit No 230298
Date Issued 11/26/2013 Date Expires 11/26/2015